


Fig.2








Fig.3




Fig.4

CHANGE IN SURFACE ROUGHNESS BEFORE AND AFTER HEAT TREATMENT IN VACUUM










Fig.5


(a)



(b)



















1000 000








Fig.9




Fig.10

